

DEPARTMENT OF DEVELOPMENT SERVICES

Development Services Center – 401 N. Elm Street – Denton, Texas 76201 voice: (940) 349-8541 www.cityofdenton.com

City of Denton Historic Landmark Commission Tax Exemption Application for Designated Historic Sites

Name of Owner	TJD Holdings, LLC									
Property Address	1314 N Locust St., Denton, Texas 76201									
Telephone/Email	940-387-0512									
Start/Completion Dates start: 01/27/2323 - finish: 03/09/2023										
	f Completed Improvements and/or Restoration Work:									
Circumferential water	drainage system, foundation repair and electrical (for water pumps).									
Please also attach t	the following with your application:									
receipts for	proof of payment for completed improvements and/or restoration work. (Please note all work completed must total a minimum of \$10,000 in order to be considered for the Historic Sites Tax Exemption.);									
2. Provide a leg	gal description of the property proposed for certification; and									
	e, a Copy of a COA Approval Letter and/or an Issued Building Permit. All exterior repairs must have an approved Certificate of Appropriateness to qualify for the tax									
knowledge and gra to provide any ad Services Departme	olication, I certify that the above information is correct and complete to the best of my ont staff access to the indicated property to perform work related to this request. I agree ditional information necessary for this application as requested by the Development or Historic Landmark Commission.									
SIGNATURE:	Jan Delsema									
Print or Type Name	: Tim DEPALMA									
Known to me to lacknowledged to me	be the person whose name is subscribed to the above and foregoing instrument, and that they executed the same for the purposes and consideration expressed and in the capacity n under my hand and seal of office on this 24th day of									

CHRISTIAN GARCIA

My Notary ID # 132674300 Expires September 14, 2024

last Updated: March 31, 2021

Notary Public Signature

DENTON

DEPARTMENT OF DEVELOPMENT SERVICES

Development Services Center – 401 N. Elm Street – Denton, Texas 76201 voice: (940) 349-8541 www.cityofdenton.com

City of Denton Historic Landmark Commission Tax Exemption Application for Designated Historic Sites

HISTORIC TAX EXEMPTION QUALIFYING IMPROVEMENTS AND/OR RESTORATION

Permanent renovation and repair of said property, shall include but not limited to the following items:

Exterior

- Protective treatment (paint, protective coverings or treatment, siding, and metal cladding)
- Structural members
- Foundations
- Exterior walls
- Roofs and drainage (roof drains, gutters, and downspouts)
- Decorative features (cornice, corbels, trim, and decorative features)
- Overhang extensions (canopies, and metal awnings)
- Stairways, decks, porches, or balconies
- Chimneys
- Handrails and guards
- Window, skylight, doors, and door frames

Interior

- Structural members
- Interior surfaces (paint and plaster)
- Stairs and walking surfaces
- Handrails and guards
- Interior doors

General

- Plumbing (re-piping, water heater, and sanitary sewer)
- Mechanical (furnace, heaters, and ventilation)
- Electrical (service and re-wiring)
- Fire safety (smoke detectors, carbon monoxide detectors)

ALL EXTERIOR RENOVATIONS/REPAIRS MUST HAVE AN APPROVED CERTIFICATE OF APPROPRIATENESS TO QUALIFY FOR THE TAX EXEMPTION.

Return to: Planning Department, 401 N. Elm Street, Denton, Texas, 76201 Phone: 940-349-8541 Fax: 940-349-7707

Last Updated: March 31, 2021

Denton CAD

Property Search Results > 33588 TJD HOLDINGS LLC for Year 2023

Tax Year

2023 - Values not available

Property

Account

Property ID:

33588

Legal Description: A0185A BBB & CRR, TR 19, .27 ACRES, OLD

DCAD TR 189

Geographic ID: Type:

A0185A-000-0019-0000 Real

Zoning: Agent Code: Office 788754

Property Use Code:

OF002

Property Use Description: CONVERTED HOUSE

Location

Address:

1314 N LOCUST ST

DENTON, TX 76201-3038

Mapsco:

Neighborhood:

Denton Converted Houses Elm & Locust Area Map ID:

Neighborhood CD:

OF02S05B2

Owner

Name:

TJD HOLDINGS LLC

Owner ID:

988655

Mailing Address:

6130 WILDCAT RD

% Ownership:

100.0000000000%

AUBREY, TX 76227-8604

Exemptions:

Values

(+) Improvement Homesite Value: N/A (+) Improvement Non-Homesite Value: N/A (+) Land Homesite Value:

(+) Land Non-Homesite Value:

N/A N/A Ag / Timber Use Value

(+) Agricultural Market Valuation: (+) Timber Market Valuation:

N/A N/A N/A N/A

(=) Market Value: N/A

(-) Ag or Timber Use Value Reduction:

N/A

N/A

(=) Appraised Value:

N/A

(-) HS Cap:

N/A

(=) Assessed Value:

Taxing Jurisdiction

Owner:

TJD HOLDINGS LLC

% Ownership: 100.0000000000%

Total Value:

N/A

Entity	Description	Tax Rate	Appraised Value	Taxable Value	Estimated Tax
C05	DENTON CITY OF	N/A	N/A	N/A	N/A
CAD	DENTON CENTRAL APPRAISAL DISTRICT	N/A	N/A	N/A	N/A
G01	DENTON COUNTY	N/A	N/A	N/A	N/A
S05	DENTON ISD	N/A	N/A	N/A	N/A
	Total Tax Rate:	N/A			
			Taxes	w/Current Exemptions:	N/A
			Taxes	w/o Exemptions:	N/A

Improvement / Building

Improvement #1: Commercial State Code: F1 Living Area: 1764.0 sqft Value: N/A

Type Description Class Exterior Year Built SQFT MA MAIN AREA 520 Wood 1913 1764.0

Improvement #2: Commercial State Code: F1 Living Area: sqft Value: N/A

Type Description Class Exterior Year Built SQFT PV PAVING CON 1990 3808.0

Land

#	Type	Description	Acres	Sqft	Eff Front	Eff Depth	Market Value	Prod. Value
1	6	COMMERCIAL	0.2700	11761.00	11761.00	1.00	N/A	N/A

Roll Value History

Website version: 1.2.2.33

Year	Improvements	Land Market	Ag Valuation	Appraised	HS Cap	Assessed
2023	N/A	N/A	N/A	N/A	N/A	N/A
2022	\$166,585	\$176,415	0	343,000	\$0	\$343,000
2021	\$173,208	\$58,805	0	232,013	\$0	\$232,013
2020	\$173,208	\$58,805	0	232,013	\$0	\$232,013
2019	\$178,865	\$58,805	0	237,670	\$0	\$237,670
2018	\$144,712	\$58,805	0	203,517	\$0	\$203,517
2017	\$132,051	\$58,805	0	190,856	\$0	\$190,856
2016	\$130,324	\$58,805	0	189,129	\$0	\$189,129
2015	\$129,493	\$58,805	0	188,298	\$0	\$188,298
2014	\$123,950	\$58,805	0	182,755	\$0	\$182,759
2013	\$119,328	\$58,805	0	178,133	\$0	\$178,133
2012	\$119,587	\$58,805	0	178,392	\$0	\$178,392
2011	\$119,172	\$58,805	0	177,977	\$0	\$177,977
2010	\$117,850	\$58,805	0	176,655	\$0	\$176,655
2009	\$121,877	\$58,805	0	180,682	\$0	\$180,682

Deed History - (Last 3 Deed Transactions)

#	Deed Date	Туре	Description	Grantor	Grantee	Volume	Page	Deed Number
1	3/20/2018	SWD	SPECIAL WD WITH VENDOR'S LIEN	FICKEY FAMILY PROPERTIES LLC	TJD HOLDINGS LLC			2018-31955
2	11/18/2009	WD	WARRANTY DEED	FICKEY FAMILY PROPERTIES, FLP	FICKEY FAMILY PROPERTIES LLC			2009-134218
3	12/18/2003	QD	QUIT CLAIM DEED	FICKEY, GAYLEN Z	FICKEY FAMILY PROPERTIES, FLP			03-203972

Questions Please Call (940) 349-3800

This year is not certified and ALL values will be represented with "N/A".

Database last updated on 3/20/2023 10:10 PM

N. Hairis Computer Corporation



Date:

December 26, 2022

Job No.: 22-1147

Job Location:

Mail To:

Name:

Mr. Timothy Depalma

Email: timdepalma@gmail.com

Address:

1314 N. Locust St,

and invasive testing. Additional fees are required.)

Phone: 214-514-8528

City: Denton, TX 76201

THIS IS TO CERTIFY THAT ON THIS DATE, I MADE AN ON-SITE INSPECTION OF THE FOUNDATION AND DRAINAGE PERFORMANCE FOR THE ADDRESSED PROPERTY. THE SUBJECT IS A ONE STORY, DENTAL OFFICE, SIDING VENEER DWELLING, SUPPORTED ON A PIER-AND-BEAM FOUNDATION. FOR ORIENTATION PURPOSES, IT IS ASSUMED THAT THE PROPERTY FACES WEST. THIS INSPECTION MEETS THE REQUIREMENTS OF A "LEVEL B" EXAMINATION AS DEFINED BY THE TEXAS BOARD OF PROFESSIONAL ENGINEERS. (Pier-and-beam foundations may require a "Level C" examination, which includes as built drawings of the foundation and locations of existing and damaged piers, and details of rotted beams, joists, and sill plates. This inspection may take between 4 to 8 hours, depending on the size of the building,

SUMMARY OF OBSERVATIONS

Foundation

- This foundation is a pier and beam type with reinforced concrete piers, perimeter brick beams and a structural grade timber floor system. It is constructed on native clay soil. It has been repaired previously.

Exterior

- The grade is relatively flat along the North side and hold surface water.
- The grade all around the residence has low spots and hold surface water.
- Crack on the exterior brick perimeter beam.

Interior

- Adjusted doors.
- Cracks on the walls.
- Cracks at the corner of doors.
- Uneven interior floor.

Crawl space

- Footings are leaning and are not supported on the beams.
- Rotted joists at the Center and Northeast side (14 of them) in the Crawl space.



FOUNDATION ELEVATION SURVEY

A "Relative Elevation Survey" was performed on the finished floor surface of the foundation of the structure using a surveying instrument. The survey is relative and is not referenced to a permanent benchmark. The purpose of the survey is to measure and document local levelness of distress areas of the foundation of the structure. Relative elevations indicated in the plan have been adjusted to account for a change in floor elevations due to dissimilar floor finishes, i.e., the elevations in all rooms or other spaces within the structure are corrected to the same plane. The elevations provide field information in order to develop a topographical surface of the foundation with respect to a horizontal plane.

The elevation survey for the foundation of the structure was performed using a Stanley® electronic compulevel® instrument. Raw elevation readings were measured at selected locations to the nearest 1/10-inch. Closure was checked by taking the last measurement at the reference point resulting in a difference of 0 inches. Instrumentation error is specified by the manufacturer at less than 1/8 inch in 100 feet radius.

The reference point for the residence was selected near the entrance door. The survey shows a differential elevation of 2.9 inches between the East Central and Northeast sides of the slab.

Soil / Foundation Interaction, General

Settlement of a foundation will typically occur under these conditions:

- 1. Shrinkage of the soil supporting the foundation due to lack of moisture. As soil shrinks, its load bearing capacity is reduced to less than the load imposed by the structure.
- 2. Loss of moisture from within the soil resulting in soil consolidation. This may occur when shrubs and trees around the foundation absorb moisture from the underlying clays through their root system or by evaporation of moisture within the near surface soil. Absence of proper maintenance such as watering the yard around the foundation, would aggravate this condition.
 - Compaction and consolidation of fill dirt under the load that is imposed by the foundation and the superstructure. This is a continuing and time dependent process that will cause settlement of the foundation unless proper precautions have been taken during the construction of the foundation.
- 3. Erosion under the floating slabs of warehouses can cause major settlement.

Heaving of the foundation may occur either under the edge lift or center heave conditions. Amount of edge heave will vary depending on the edge moisture variation distance. If the moisture content of the soil beneath the slab changes after construction of the slab, it will distort into either a center lift or edge lift condition. Center heave lift condition occurs when the soil beneath the interior of the slab becomes saturated and expands, or when the soil around the perimeter of the slab dries and shrinks while the soil under the interior slab remains wet.



Heave may also occur as a result of a long-term leak in pressure or sewer lines where moisture is drawn to the soil under the slab through the suction properties of the soil. Location of heave depends on the nature of the soil supporting the slab and may not necessarily be in the same area as the leak.

It should also be noted that depending on the nature and consolidation rate of the clay particles, when the soil becomes saturated, the clay binders lose their shear strength and hence undergo a structural collapse, which results in a foundation settlement. However, if the soil is well compacted or normally consolidated, then saturation may result in a swell process, causing the foundation to experience upheaval. Furthermore, when a saturated incompressible compacted clay layer is subjected to a stress increase, swelling rather than settlement may occur, but when a saturated compressible clay layer is subjected to a stress increase, elastic settlement occurs immediately. The following conclusions and recommendations apply to the inspected areas only.

CONCLUSION

- This foundation experiences a combination of settlement and heave. Settlement along the North and West sides of the residence is due to shrinkage of the expansive soils supporting the foundation in this area. It requires repair at the present time. The cause of the upheaval along the Southeast and East sides of the residence is poor surface drainage.

RECOMMENDATION

- Regrade and contour the soil all around the foundation perimeter to provide positive slope. Add clean black top soil to fill low spots as required. The new grades should cause positive surface drainage away from the foundation to a minimum distance of 4 feet. Upon completion, the exposed concrete perimeter beam should be from 6" to 8". Level the floor by shimming on the existing piers. Proper re-leveling includes replacement of any structural members which are not performing their intended function wherever encountered in the crawl space. This includes any twisted or displaced members or any wood that has been damaged by rot or wood destroying insects.
- Install a French drain around the perimeter in the approximate location shown on the attached sketch. The depth of the trench should be a minimum of 36" below the bottom of the perimeter beam with 12" width. The pipe should be 6" diameter, perforated "ADS" pipe wrapped in geotextile cloth as a filter to provide longer service life of the drains. Cover the pipes with washed gravel (6" on bottom and 30" on top) with normal fill dirt on top. Connect the perforated pipe to 6" solid pipe to slope the drain lines at least 1/8" per foot to discharge based on gravitational forces to the locations shown on the attached sketch.
- Remove and replace the rotted joists at the Center and Northeast side (14 of them) in the Crawl space.
- Remove and replace the brick perimeter beam with concrete beam (36"x10", reinforced with #4 rebar up and down section of beam, concrete mix should have minimum 3000 Psi compaction strength).
- Install concrete footings under the beams to provide adequate supports in the crawl space.



- Specifications of footings 24"x24"x12" reinforced with #4 rebar at 8" O.C both ways concrete 4000 Psi Sonotube on the footings.
- Connect the downspouts to a 6" diameter pipe to drain to either parking lot or streets around as indicated on attached sketch.
- Level the floor by shimming on the existing piers. Proper re-leveling includes replacement of any structural members which are not performing their intended function wherever encountered in the crawl space. This includes any twisted or displaced members or any wood that has been damaged by rot or wood destroying insects.
- This foundation should be inspected again at the end of dry season in order to evaluate the impact of the drainage correction on the stability of the foundation and to recommend the remedial measures if it is required.
- All the work should be certified by a structural engineer.

NOTE:

- IN THE EVENT THAT OTHER INFORMATION BECOMES AVAILABLE THAT COULD AFFECT THE CONCLUSION REACHED IN THIS INVESTIGATION, THIS OFFICE RESERVES THE RIGHT TO REVIEW AND CHANGE SOME OR ALL OF THE OPINONS REPRESENTED HEREIN, IF IT IS REQUIRED

This inspection consists of visual observations only and is based on engineering judgment, made solely to determine the foundation and drainage problem(s) of the described property at the present time. This report does not predict or warrant the future performance of the inspected foundation.

The portion of the foundation which is inspected is readily visible without moving or removal of any items that may cause a visual obstruction. In other words, this report is based solely on observation of the apparent behavior of the structure.

Opinions expressed in this report are based on an engineering evaluation considering past performance of the structure. It is assumed that the foundation was constructed based on the requirements of building codes and was inspected by local building officials during construction. No warranty is either expressed or implied as to the future performance of this structure. Liability is strictly limited to the fee charged for this report.

In order to certify the repair works that are performed based on our specifications, the works should be inspected after the pier holes are ready and rebar is in place, and again after raising and before backfilling of the pier holes (this is to check that proper leveling of the foundation has been done). The new elevations will be our reference for monitoring the future movement, if any, of the foundation. These inspections require advance scheduling; therefore, the engineer should be informed at least 48 hours prior to the commencement of repair work. Additional engineering fees will be charged for this service, which is **not** included in the fee for this report.



This inspection is not intended to cover structural features above foundation level. This report merely covers the status of the foundation at the time of this inspection.

Should you require a more in-depth study such as soil test, stress analysis and redesign, you need only to advise our office. A reasonable fee will be quoted based on normal hourly charges for engineering and consulting services.


It has been our pleasure to perform this work for you. If you need further assistance, please do not hesitate to call us. Thank you.


NICK MANESH

MICHAE

NICK MANESH, Ph.D., PE REGISTERED PROFESSIONAL ENGINEER, STATE OF TEXAS

TBPE FIRM NUMBER 17151





Dallas, TX 75252 p:(469) 615-0430 f:(972) 865-1354 NICK MANESH ENGINEERING, 17630 Davenport Rd., Suite #109

T.B.P.E. # F-17151

ISSUE RECORD:

ISSUED FOR:

PRIVATE RESIDENCE 1314 N. Locust Street, Denton, TX 76201

SHEET CONTENTS:

Drainage Details DATE: 12-26-2022

SECTION A-A: Drainage Trench with Perforated & Solid Pipe SCALE: 1-1/2" = 1'-0"

AB

Ali Bahrami

December 23, 2022 · Money Sent

- \$797.78

Paid with

Contact info

\$797.78Message Ali Bahrami

Foundation

Note

You'll see

"PAYPAL

*bahrami81"

on your card

statement.

Transaction ID

6LK28311VK976570G

Details

Sent to Ali Bahrami

\$775.00


Fee

\$22.78

Total

\$797.78







Inspection requested for 1314 N Locust StDenton, TX 76201

Inbox



Nick Manesh <nickmanesh.asi@gmail.com> to me

Wed, Dec 21, :

Dear Mr. Depalma,

As per your request we can schedule to perform this inspection on Tuesday Dec 27th at 10:30am. The following veriformed during this inspection:

- Foundation Inspection
- Crawl space Inspection
- Drainage Inspection
- Interior/Exterior wall Inspection
- CAD drawing
- Fully drafted report with observations, recommendations with remedial measures if required

The fee to perform this inspection is \$775. (This is due prior to the inspection date with Zelle, Paypal or cashier's This fee is only specific for the mentioned scope of work and does not include any designs, quality controls or oth inspections if required)

Please confirm and inform your method of payment so we can provide details. Also, please email us a clear copy of the residence or any previous foundation work.

Client's information:

Mr. Tim Depalma 214-514-8528

Regards,

Nick (Senior Structural Engineer, Ph.D, PE, JD)

Nick Manesh, Ph.D., PE, JD CEO and Chief Engineer



http://www.nickmaneshengineering.com



by and between BROWN FOUNDATION REPAIR, hereinafter This contract is entered into this day of 5th Jan. 2023 hereinafter called OWNER, on property located at called CONTRACTOR, and Tim Depalma 1314 N. Locust Denton Tx. 76201 Office: 214-514-8528 Phone Home: Cell: B. **Pilings** Mudjacking (Two Year Warranty) **Drilled Piers** (Lifetime Warranty) (Lifetime Service Warranty) Mudpumping (Two Year Warranty) C. Crawl Space Adjustment: (Five Year Limited Warranty) Square foot to be re-shimmed Sill Replacement Wood Replacement **Pre-Cast Piers** Beam Replacement Sole Replacement (Five Year Limited Warranty) Joist Replacement (Additional Wood Replacement may result in a \$25 per foot Charge) D. Drainage: (Two Year Warranty) 70tt Solid Pipe Root Barrier Sump Pump (Two Year Warranty) Basins Curb Cut 159f French Drain Tunnel Under Sidewalk Other: Will install appx. 159ft. of 6"dia. perforated ADS pipe french drain with filter fabric wrap around pipe. Will start appx. 18" deep per Engineers recommendation. Will set in rock up to 1ft. from surface that will be filled in with dirt. Will install plastic liner on inside edge of ditch. Will tie in downspouts into the system with solid 4" dia. ADS pipe. Will drain water out to back parking lot and to side street per diagram. Brown Foundation will install a 12" diameter steel reinforced pier approximately 9'-12' deep from ground surface or to refusal of drilling machine. Haunch base to be approximately 4 sq. ft. with an overall thickness of approximately 12". Contractor will mechanically raise perimeter beam to approximate original grade, or as practical. Then pour a 12" diameter pier between beam and haunch. It is understood and agreed that in order to perform the above described work, sheetrock, wallpaper, brick and other rigid materials may crack. Therefore, the above work estimate does not include any redecorating, repairing, electrical work, or the replacement of any materials not called for in this agreement. Contractor will repair any water and sewage lines directly damaged during excavation and drilling. Pre-existing plumbing problems, deteriorated pipes, and broken plumbing caused by lifting or mudjacking/mudpumping will not be repaired by Contractor. Contractor will temporarily remove plants and shrubs which obstruct support installation. All plants and shrubs will be replanted, however BFR is not responsible for possible damage to landscape (i.e. sod, bushes, etc.) et al. underground utilities or lawn sprinklers caused by reasonable and prudent operation of the drilling machine and/or leveling operations. All warranties issued cover settlement in area repaired under this agreement. Warranty does not cover upheaval or the influx of water. Contractor is liability insured for customer's protection. The Owner may order extra work to be done, not contemplated by this agreement, in which event a separate Agreement for such work shall be entered into between the Owner and the Contractor. No oral representation made by anyone can change or modify this Agreement. Not withstanding, any provision in this agreement to the contrary, any dispute, controversy, or lawsuit between any of the parties to this agreement about any matter arising out of this agreement, shall be resolved by mandatory and binding arbitration administered by the American Arbitration Association ("AAA") pursuant to the arbitration laws in your state and in accordance with this arbitration agreement and the commercial arbitration rules of the AAA to the extent that any inconsistency exists between this arbitration agreement and such statutes by any court having jurisdiction and in accordance with the practice of such court. MOLD AND OTHER CONTAMINANT'S: Contractor and owner expressly agree that Contractor and its employees and agents will not be liable for damages or costs of any type - the Owner will hold harmless and indemnify Contractor from any and all claims or causes of action, including negligence, arising in any way from exposure to or the presence, release, growth or origin of any microorganism, organic or inorganic contaminant including, but not limited to, mold, mildew, fungus, yeast, allergens, infectious agents, wet or dry rot, rust, or read occurring in any way as a result of the services provided and work performed. The provisions contained herein are expressly material to this Agreement and the "cost to the Owner" for the heretofore described "work" is determined in part by the agreement of the Owner to these provisions. The CONTRACTOR agrees to furnish all materials, labor and insurance required to perform the following items of (WORK): The OWNER agrees to pay CONTRACTOR the sum of (5 18,500.00), payable as follows: 1) \$ 9,250.00 upon commencement of work. 2) \$ 9,250.00 upon completion. The undersigned represents that he is (they are) the owners of the above mentioned premises and that the legal title thereto stands of record in his (her) or IN FOUNDATION LEVELING, CONDITIONS MIGHT APPEAR WHEN WORK IS BEGUN THAT WERE NOT VISIBLE WHEN ESTIMATE WAS SUBMITTED, SUCH AS INSUFFICIENT REINFORCING STEEL IN CONCRETE SLAB AND/OR OTHER ORIGINAL FOUNDATION STRUCTURAL DEFICIENCY. IN SUCH CASE, THE GUARANTEE. BECOMES INVALID. Lee Wormington Owner Salesman

Manager

Owner



by and between BROWN FOUNDATION REPAIR, hereinafter This contract is entered into this day of Jan. 2023 6th hereinafter called OWNER, on property located at called CONTRACTOR, and Tim Depalma 1314 N. Locust St. Denton Tx. 76201 214-514 8528 Office: Cell: Phone Home: Mudjacking (Two Year Warranty) **Drilled Piers** B. Pilings (Lifetime Service Warranty) (Lifetime Warranty) Mudpumping (Two Year Warranty) C. Crawl Space Adjustment: (Five Year Limited Warranty) Sill Replacement Square foot to be re-shimmed Wood Replacement Sole Replacement 21 Pre-Cast Piers Beam Replacement (Five Year Limited Warranty) 112f Joist Replacement (Additional Wood Replacement may result in a \$25 per foot Charge) D. Drainage: (Two Year Warranty) Solid Pipe Sump Pump **Root Barrier** (Two Year Warranty) Basins Curb Cut French Drain Tunnel Under Sidewalk Other: Will install 21 new mono piers beside existing precast pads that are leaning. Will shim off existing piers with metal shims as needed. Will scab onto appx.112ft. of 2x6 joist. Any additional rotted wood if needed would 45.00 per ft. We will take picture of the wood and would have to be approved by owner. Bid per Nick Manesh Engineering report excluding removing all brick beam and pouring new concrete beam. Will carry a 10yr. warranty on mono piers. Brown Foundation will install a 12" diameter steel reinforced pier approximately 9'-12' deep from ground surface or to refusal of drilling machine. Haunch base to be approximately 4 sq. ft. with an overall thickness of approximately 12". Contractor will mechanically raise perimeter beam to approximate original grade, or as practical. Then pour a 12" diameter pier between beam and haunch. It is understood and agreed that in order to perform the above described work, sheetrock, wallpaper, brick and other rigid materials may crack. Therefore, the above work estimate does not include any redecorating, repairing, electrical work, or the replacement of any materials not called for in this agreement. Contractor will repair any water and sewage lines directly damaged during excavation and drilling. Pre-existing plumbing problems, deteriorated pipes, and broken plumbing caused by lifting or mudjacking/mudpumping will not be repaired by Contractor. Contractor will temporarily remove plants and shrubs which obstruct support installation. All plants and shrubs will be replanted, however BFR is not responsible for possible damage to landscape (i.e. sod, bushes, etc.) et al. underground utilities or lawn sprinklers caused by reasonable and prudent operation of the drilling machine and/or leveling operations. All warranties issued cover settlement in area repaired under this agreement. Warranty does not cover upheaval or the influx of water. Contractor is liability insured for customer's protection. The Owner may order extra work to be done, not contemplated by this agreement, in which event a separate Agreement for such work shall be entered into between the Owner and the Contractor. No oral representation made by anyone can change or modify this Agreement. Not withstanding, any provision in this agreement to the contrary, any dispute, controversy, or lawsuit between any of the parties to this agreement about any matter arising out of this agreement, shall be resolved by mandatory and binding arbitration administered by the American Arbitration Association ("AAA") pursuant to the arbitration laws in your state and in accordance with this arbitration agreement and the commercial arbitration rules of the AAA to the extent that any inconsistency exists between this arbitration agreement and such statutes by any court having jurisdiction and in accordance with the practice of such court. MOLD AND OTHER CONTAMINANTS: Contractor and owner expressly agree that Contractor and its employees and agents will not be liable for damages or costs of any type - the Owner will hold harmless and indemnify Contractor from any and all claims or causes of action, including negligence, arising in any way from exposure to or the presence, release, growth or origin of any microorganism, organic or inorganic contaminant including, but not limited to, mold, mildew, fungus, yeast, allergens, infectious agents, wet or dry rot, rust, or read occurring in any way as a result of the services provided and work performed. The provisions contained herein are expressly material to this Agreement and the "cost to the Owner" for the heretofore described "work" is determined in part by the agreement of the Owner to these provisions. The CONTRACTOR agrees to furnish all materials, labor and insurance required to perform the following items of (WORK): The OWNER agrees to pay CONTRACTOR the sum of (5 28,700.00) payable as follows: 1) \$ 14,350.00 upon commencement of work. 2) \$ 14,350.00 upon completion. The undersigned represents that he is (they are) the owners of the above mentioned premises and that the legal title thereto stands of record in his (her) or IN FOUNDATION LEVELING, CONDITIONS MIGHT APPEAR WHEN WORK IS BEGUN THAT WERE NOT VISIBLE WHEN ESTIMATE WAS SUBMITTED, SUCH AS INSUFFICIENT REINFORCING STEEL IN CONCRETE SLAB AND/OR OTHER ORIGINAL FOUNDATION STRUCTURAL DEFICIENCY. IN SUCH CASE, THE GUARANTEE BECOMES INVALID. Lee Wormington Salesman Owner

Owner

Transaction Receipt from Brown Foundation Repair for \$8250.00 (

Inbox ×



Auto-Receipt <noreply@mail.authorize.net>

to me

Mon, I

Thank you for choosing Brown Foundation Repair.

Order Information

Description:

Second Half

Billing Information

Shipping Information

Tim Depalma

1314 North Locust St.

1314 North Locust St.

76201

76201

timdepalma@gmail.com

Total: \$8250.00 (USD)

Payment Information

Date/Time:

6-Feb-2023 8:50:56 CST

Transaction ID:

43924588273

Payment Method:

Transaction Type:

Purchase

Auth Code:

892934

Merchant Contact Information
Brown Foundation Repair

Dallas, TX 75229

US

gbrown@brownfoundationrepair.com

Merchant: Brown Foundation Repair

1619 Bluebank RD Dallas, TX 75229 US

(972) 271-2621

Cross Information

Description:

Deposit for 1314 N Locust St

Order Number: Customer ID:

P.O. Number:

Invoice Number:

Shipping Information

1314 N Locust St. 76201

Billing Information

1314 N Locust St. 76201 Tim DePalma

timdepalma@gmail.com

Shipping:

0.00 0.00

Total: USD 1,500.00

Payment Information

06-Jan-2023 16:43:26 CST Date/Time:

43864741194 Transaction ID: Authorization w/ Auto Capture Settled Successfully Transaction Status: Transaction Type:

Authorization Code:

Payment Method:

791566

Transaction Receipt from Brown Foundation Repair for \$9250.00 (

Inbox x



Auto-Receipt <noreply@mail.authorize.net>

Fri, Ja

to me

Thank you for choosing Brown Foundation Repair.

Order Information

Description:

1st half for 1314 N Locust St

Billing Information

Shipping Information

Marissa Depalma

1314 N Locust St.

1314 N Locust St.

76201

76201

timdepalma@gmail.com

Total: \$9250.00 (USD)

Payment Information

Date/Time:

27-Jan-2023 10:04:02 CST

Transaction ID:

43900814410

Payment Method:

Transaction Type:

Purchase

Auth Code:

499595

Merchant Contact Information

Brown Foundation Repair

Dallas, TX 75229

US

gbrown@brownfoundationrepair.com

Transaction Receipt from Brown Foundation Repair for \$14100.00 (USD)

Inbox



Auto-Receipt <noreply@mail.authorize.net> 9:59 AM (24 minutes ago)

to me

Thank you for choosing Brown Foundation Repair.

Description:

First Half for 1314 N Locust

Billing Information

Tim Depalma

1314 N Locust St

76201

timdepalma@gmail.com

Shipping Information

1314 N Locust St

76201

Total: \$14100.00 (USD)

Date/Time:

6-Mar-2023 9:59:38 CST

Transaction ID:

43979236162

Payment Method:

Transaction Type:

Purchase

Auth Code:

261062

Brown Foundation Repair Dallas, TX 75229

gbrown@brownfoundationrepair.com

Transaction Receipt from Brown Foundation Repair for \$14100.00 (USD)

Inbox



Auto-Receipt <noreply@mail.authorize.net> Fri, Mar 10, 2:37 PM (4 days ago)

to me

Thank you for choosing Brown Foundation Repair.

Order Information

Description:

2nd half for 1314 N Locust St

Billing Information

Tim Depalma

1314 N Locust St

76201

timdepalma@gmail.com

Shipping Information

1314 N Locust St

76201

Total: \$14100.00 (USD)

Payment Information

Date/Time:

10-Mar-2023 14:37:39 CST

Transaction ID:

43989049424

Payment Method:

Transaction Type:

Purchase

Auth Code:

731064

Merchant Contact Information

Brown Foundation Repair Dallas, TX 75229

US

gbrown@brownfoundationrepair.com

A. H. Electrical Service, Inc. P.O. Box 1338 Denton TX 76202

03/20/2023

SALE Total: \$775.00

Exp. Date: xx / xx

Entry Mode: Keyed

Name: DePalma Family Dentistry

Auth. Code: 359596 QuickBooks Trans. No: Trans. ID: MU0148748631 Merchant No.:

Terminal ID: - AID -

No additional transfer fees or taxes apply

Thank you for your business

5247710000073221

Payment services brought by:

Intuit Payments Inc. 2700 Coast Avenue, Mountain View, CA 94043 Phone number 1-888-536-4801 NMLS #1098819

For more information about Intuit Payments' money transmission licenses, please visit https://www.intuit.com/legal/licenses/payment-licenses/

CUSTOMER COPY

New Water Pumps & Drainage System







New Water Pumps & Drainage System







New Drainage System





