

1988- Station 5 - 2230 W Windsor

Facility Stats

- 8,033 sq. ft. - Living/support: 4,044 - Bays 4,000
- 6 Personnel per shift
- Houses Quint, Medic, Brush, HazMat




Station 5 Challenges

- Lack of private sleeping/dressing/restroom/showering area
- **Lack of cancer reduction zones (hot/warm/cold)***
- **No dedicated storage for personal protective gear***
- **Ineffective ventilation and heaters in apparatus bays***
- Lack of emergency generator to fully power the fire station
- Slow-opening horizontal bay doors
- No secured employee parking
- Rodent remediation 2013 and 2023
- Impacted by new Denton High School traffic

* denotes CFAI Accreditation Recommendation



Station 5 Calls for Service 2022



2022 Total Unit Responses
6,273

Average of 17
responses per day



1991- Station 6 - 3232 Teasley Ln

Facility Stats

- 5,995 sq. ft. - Living/support: 3596 - Bays 2,400
- 5 Personnel per shift
- Houses Engine, Medic




Station 6 Challenges

- Lack of private sleeping/dressing/restroom/showering area
- **Lack of cancer reduction zones (hot/warm/cold)***
- **No dedicated storage for personal protective gear***
- **Ineffective ventilation and heaters in apparatus bays***
- Lack of emergency generator to fully power the fire station
- Slow-opening horizontal bay doors
- No secured employee parking
- Rodent remediation 2013
- Blind response exit
- Back-in required to park apparatus

* denotes CFAI Accreditation Recommendation



Station 6 Calls for Service 2022



2022 Total Unit Responses
4,925

Average of 13.5
responses per day