



5000 AIRPORT RD. • DENTON, TEXAS 76207 • (940) 349-7736 • FAX (940) 349-7289
DENTON ENTERPRISE AIRPORT • DTO

MONTHLY OPERATIONS REPORT February 2025

The following tables provide details on operations, fueling, based aircraft, alerts, incidents, and wildlife management efforts. Historical Airport Operations, **Exhibit 1**, and Historical Fuel Flowage, **Exhibit 2**, provide airport historical operations and fuel flowage data from 2014-2024.

OPERATIONS (Calendar Year)						
Operation Type	Dec-23	Dec-24	% Change	2023 YTD	2024 YTD	% Change
IFR Itinerant	748	1,098	46.8%	9,387	12,182	29.8%
VFR Itinerant	6,921	6,949	0.4%	83,845	103,413	23.3%
Local	10,308	6,566	-36.3%	118,968	106,351	-10.6%
Total	17,977	14,613	-18.7%	212,200	221,946	4.6%

FUELING (Fiscal Year)						
Type	Dec-23	Dec-24	% Change	2023 YTD	2024 YTD	% Change
AvGas	33,729	50,867	50.8%	118,087	163,053	38.1%
Jet A	87,840	79,863	-9.1%	301,406	245,863	-18.4%
Total	121,569	130,730	7.5%	419,493	408,916	-2.5%

BASED AIRCRAFT					
Description	Single Engine	Multi-Engine	Jet	Helicopter	Total
Dec 2024	352	71	35	18	476
Dec 2023	309	62	34	15	420
Dec 2022	321	79	38	14	452

NOTE: Due to agenda-related deadlines, figures for the prior month will be available at the next Airport Advisory Board meeting.

Monthly Operations Report
February 2025
Page 2

ALERTS		
Date	Type	Description
N/A		

INCIDENTS	
Date	Description
12/30/2024	A pilot in a 172 reported a flat nose wheel in the A7 runup area. Mechanic was able to change the tire in the runup area and the aircraft carried on with their scheduled flight.
1/03/2025	A pilot in a 177 reported a flat nose wheel in the A7 runup area. The aircraft was towed back to parking without further incident
1/16/2025	A pilot reported a minor leak at the self-serve fuel pump near Taxilane Foxtrot. Airport Ops responded with Sheltair right away and noticed the leak was due to a loose fitting that was not tightened all the way after the tank was sumped that morning. The leak was of no significant size, so no reporting was needed.
1/22/2025	A pilot in a 172 reported a flat nose wheel on RWY 18L. Mechanic was able to quickly change the tire on the runway and the aircraft was able to taxi to parking.
1/23/2025	A pilot in a 172 reported a flat nose wheel in the A7 runup area. Mechanic was able to change the tire in the runup area and the aircraft carried on with their scheduled flight.

DECEMBER WEATHER DATA	
Days with Measurable Precipitation	Days with an Avg. Wind over 10mph
10	10

EXHIBITS

1. Historical Airport Operations 2014-2024 (Attached)

DENTON ENTERPRISE AIRPORT HISTORICAL OPERATIONS

Month:	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024
JAN	11019	14419	12074	11070	13036	12323	9830	9138	14030	13814	14618
FEB	10023	10891	12530	9300	7899	9307	11704	6697	10469	13218	20919
MARCH	13929	12886	9240	10846	10659	13074	10055	12423	12719	15134	21655
APRIL	14788	12816	10226	9390	11314	11709	12090	10631	13601	14993	16992
MAY	16140	12431	11958	11914	14854	11172	12690	10704	9902	19470	19503
JUNE	12949	15308	11962	10342	12521	12468	11282	11519	15321	18549	22043
JULY	14912	17359	13190	11162	13553	11718	14274	14124	15936	19931	13869
AUG	13558	18143	11461	10514	14888	10392	13076	12868	17597	21408	14855
SEP	13485	14665	13523	11010	11477	12176	10911	13672	20217	20484	20090
OCT	14334	13208	13021	10870	13682	11444	11445	12837	17794	18362	23875
NOV	10974	10906	9195	10249	13276	11367	10508	12482	14415	18860	18914
DEC	11228	12020	9166	10899	11539	11379	10296	12051	14217	17977	14613
Total:	157339	165052	137546	127566	148698	138529	138161	139146	176218	212200	221946

