

EXHIBIT 1



February 27, 2017

Monty Perry
Captain
Denton Fire Department
monty.perry@cityofdenton.com

Quote # 393
HGAC Contract# AM10-14

Captain Perry,

Per your request we are quoting remounting and refurbishing your Frazer Type I 12' Generator Powered Module (E-2314) onto a 2017 Chevrolet C3500 6.7L diesel chassis (order Chevy Red)with a LiquidSpring suspension system. For your convenience all pricing has been itemized below.

| | |
|-------------------------------------------------------------|----------------------|
| Frazer Type I 12' Generator Powered Module (E-2314) | |
| 2017 Chevrolet C3500 6.7L diesel chassis (order Chevy Red) | \$ 44,750.00 |
| Granning suspension | \$ 7,000.00 |
| Heat Shielding for diesel chassis | \$ 1,500.00 |
| Remount of Module (see Incl. Items below) | \$ 18,000.00 |
| Chassis Exterior Upgrades | \$ 1,800.00 |
| Chassis Interior Upgrades | \$ 1,800.00 |
| Module Exterior Upgrades | \$ 38,600.00 |
| Module Interior Upgrades | \$ 55,850.00 |
| Total | \$ 169,300.00 |

Items included in above total:

Chassis Exterior Upgrades:

| | | |
|------------------------------------------------------|----|--------|
| 1 . Items included in remount fee: | \$ | incl. |
| a) Black Ranch Hand powder coated grille guard | | |
| b) (2) Whelen M6 split grille lights w/ clear lenses | \$ | 150.00 |

EXHIBIT 1

Layout: C/R-C/R

- | | | |
|------------------------------------------------------|----|--------|
| c) (2) Whelen M6 split grille lights w/ clear lenses | \$ | 150.00 |
|------------------------------------------------------|----|--------|

Layout: C/R-C/R

- d) (2) Federal Signal AS124 speakers
- e) Frazer aluminum rear window pass through plate
- f) (2) New 125A & 150A Mega fuses with new wiring
- g) Stripe new chassis to match module
- h) New mounting rubber
- i) New tie downs & spacers
- j) Furnish & install Backup alarm

Note: Backup alarm kill relay on Chevy C3500/K3500

- k) Mud flaps
- l) Old chassis is wrecked-notify Sales when unmounted so customer can send a wrecker to pick up
- m) This unit needs to be weighed and a weight slip provided to the customer
- n) This unit needs state inspection
- o) Fuel with diesel to verify fuel flow
- p) Issue temporary license plate
- q) Wash Unit
- r) Route chassis exhaust to below P/S bumper end cap
- s) Furnish and install stainless steel wheel covers

- | | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|----------|
| 2 . Furnish & install black Nerf bars | \$ | 450.00 |
| 3 . Furnish & install single Buell 10"airhorn through front bumper on P/S of the license plate with truck horn reconnect to existing compressor. Air horn operated by truck horn/air horn switch on the console. | \$ | 1,050.00 |
| a) Furnish & install Truck horn/airhorn switch at the console | | |
| b) Remove & reinstall existing compressor below the shelf in the electrical compartment | | |
| c) Furnish & install air tank | | |

| | | |
|--------------|-----------|-----------------|
| Total | \$ | 1,800.00 |
|--------------|-----------|-----------------|

Chassis Interior Upgrades

- | | | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|--------|
| 4 . Furnish & install pinned powder coated aluminum six position console | \$ | incl. |
| a) Slot 1/2: Double Switch Panel with genset fuel gage | | |
| <i>Layout: PRIMARY – SECONDARY – OPTICOM – TUCK/AIR HORN – LOW POWER BLUE-BLANK-BLANK-INTERIOR LIGHT-REAR LOAD- SIDE SCENE (1 way switch – controls one side) – SIDE SCENE (1 way switch –controls one side) – START STOP (Genset)</i> | | |
| b) Slot 3: Federal Signal PA 300 siren in lieu of standard Whelen 295SLSA1 siren. Mic on D/S slot 1. Tap 2 on primary siren | \$ | 250.00 |
| c) Slot 4: Additional Federal Signal PA 300 siren- mic on D/S slot 2 | \$ | 600.00 |
| d) Slot 5/6: Furnish & install double blank insert | \$ | 150.00 |
| 5 . Remove and reinstall (2) small map holders on passenger side (1- centered on rear half of console and 1 centered on front half of console | \$ | 75.00 |
| 6 . Remove and reinstall (2) large map holders onthe rear of console | \$ | 75.00 |
| 7 . Furnish and install switch for the blue lights on rear of unit to be lower power/off-match previous new unit. | \$ | 250.00 |
| 8 . Remove and reinstall radio on front of console with speaker, antenna, and base. | \$ | 400.00 |

| | | |
|--------------|-----------|-----------------|
| Total | \$ | 1,800.00 |
|--------------|-----------|-----------------|

EXHIBIT 1

Module Exterior Upgrades

- 9 . Items included in remount fee: \$ incl.
- a) Install new ignition & fail safe solenoids on electrical shelf
 - b) Full electrical check
 - c) New passthrough rubber boot
 - d) Replace all door compartment bumpers
 - e) Replace weather stripping
 - f) New ribbed rubber in applicable compartments
 - g) Zero clearance behind side main entry step well
 - h) Zero clearance inside lower front I/O compartment
 - i) Verify front and rear wall skins have 10ga Black ground wire terminated to roof frame
 - j) Frazer key fob
 - k) Replace marker lights (discard old)
 - l) Furnish & install factory fuel guard (discard old)
 - m) Furnish & install Genset shutdown circuit w/ acknowledge switch at rear entry doors
 - n) Furnish and install Flexstrip LED lighting with magnetic strip in aplicable compartments (I/O, radio, rear storage, O2, long lower, and electrical) \$ incl.
- 10 . Strip, prime, and repaint 12' module Chevy Red to match and paint the roof white with the side trim white as well \$ 16,750.00

Note – Items sub-listed are included with paint unless stated otherwise

- a) Furnish & install corner caps on module
 - b) Replace compartment and entry door latches w/ Eberhard style latches
 - Install eberhard striker threshold in the O2, radio, Electrical, Rear storage, rear backboard and front I/O
 - Install A/C and Onan insert threshold
 - Install long lower storage striker threshold
 - Remove and reinstall Opticom on front wall. (non latching, on/off switch at console and off with chassis door switch)
 - c) chassis door switch)
 - d) Install new side entry door grab rail (discard old)
 - e) Install new rear entry door grab rails (discard old)
 - f) Furnish & install new side entry gas shock
 - g) Furnish & install gas shock on long lower storage compartment door
 - h) Furnish and install O2 compartment vent
 - i) Install new O2 compartment insert threshold
 - j) Furnish & install (2) 4" round red LED lower B/T/T's and (2) 4" round lower clear back up lights
 - k) Install new drip rails without rivets over the following & bondo over existing holes:
 - 1. Side entry doors
 - 2. Rear entry doors
 - l) Rear entry corner guards
 - m) Replace entry door windows with double pane windows
 - n) Remove & reinstall Kussmaul dual 20A shore power on front wall of module
- 11 . Furnish & install new doors on the following (discard old): \$ incl.
- a) O2 compartment
 - b) Radio compartment
 - c) Long lower storage compartment
 - d) Rear storage compartment

EXHIBIT 1

| | | |
|-----------------------------------------------------------------------------|----|----------|
| e) Rear passenger's side entry door | | |
| f) Rear driver's side entry door | | |
| g) Side entry door | | |
| h) Generator compartment | | |
| i) Front I/O compartment | | |
| j) A/C compartment door | | |
| k) Electrical compartment | | |
| l) Rear backboard compartment | | |
| 12 . Furnish & install new panels on the following new doors (discard old): | \$ | incl. |
| a) O2 compartment | | |
| b) Radio compartment | | |
| c) Long lower storage compartment | | |
| d) Rear storage compartment | | |
| e) Rear passenger's side entry door | | |
| f) Rear driver's side entry door | | |
| g) Side entry door | | |
| h) Front I/O compartment | | |
| i) A/C compartment | | |
| j) Electrical compartment | | |
| 13 . Furnish & install new hinges on the following doors (discard old): | \$ | incl. |
| a) O2 compartment | | |
| b) Radio compartment | | |
| c) Long lower storage compartment | | |
| d) Rear storage compartment | | |
| e) Rear passenger's side entry door | | |
| f) Rear driver's side entry door | | |
| g) Side entry door | | |
| h) Generator compartment | | |
| i) Front I/O compartment | | |
| k) Electrical compartment | | |
| l) Rear backboard compartment | | |
| j) A/C compartment | | |
| 14 . Replace entire rear bumper (discard old) | \$ | 700.00 |
| a) Driver side bumper cap | | |
| b) Center step | | |
| c) Passenger side bumper cap | | |
| d) Driver & passenger side dock bumper | | |
| e) Center bumper strip | | |
| 15 . Furnish & install treadbrite for the following (discard old): | \$ | 900.00 |
| a) Driver's & Passenger's side front corner panels | | |
| b) Passenger's side wheel well panel | | |
| c) Driver's side wheel well panel round filler guards | | |
| d) Driver side rear panel with (2) 4" round light cut outs | | |
| e) Passenger side rear panel with (2) 4" round light cut outs | | |
| f) Install rear entry threshold | | |
| 16 . This unit will get new Striping & lettering | \$ | 2,400.00 |

EXHIBIT 1

| | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|
| 17 . 3M diamond grade conspicuity fluorescent yellow/green base with red translucent overlay in a chevron pattern on entire rear of module. (see previous units) This total includes removal of existing | \$ 2,000.00 |
| 18 . Furnish and install the following decals: | \$ incl. |
| a) Install CO stickers in three (3) locations and ship (1) loose | |
| b) Install one (1) NO SMOKING sticker on dash and ship one (1) loose | |
| 19 . Remove and reinstall all emergency lights. | |
| 20 . Furnish and install Rigid 50" lightbar on front wall. | \$ 3,000.00 |
| 21 . Furnish & install (2) FRC 900 series Spectra LED side scene lights in standard location, wired to 2 switches | \$ 2,000.00 |
| <i>Note - convert wiring in electrical compartment to 12V; add plating to existing location on passenger's side</i> | |
| 22 . Furnish & install new rear entry door grabbers (discard old) | \$ 100.00 |
| 23 . Furnish & install cast LED license plate light (discard old) | \$ 100.00 |
| 24 . Furnish and install electric locks on the following doors: side/rear entry, O2, I/O, rear storage, and radio. There will be a hidden weatherproof switch at rear driver side bumper end cap and a lock/unlock switch at the action wall. The module locks will have their own key fob separate from the chassis key fob. | \$ 3,150.00 |
| 25 . Furnish & install new Onan 5.5kW generator with new non permeable hoses, emissions canister kit, new fuel pump and filter and tank | \$ 7,500.00 |
| Total | \$ 38,600.00 |

Module Interior Upgrades:

| | |
|-----------------------------------------------------------------------------------------------------------------|---------------------|
| 26 . Items included in remount fee: | \$ incl. |
| a) Replace all non-skid material on threshold(s) with 3M non-skid material (discard existing) | |
| b) Complete detail of module interior | |
| c) Air filter | |
| d) Furnish & install air filter (discard existing) | |
| 27 . Furnish and install Wise Cobalt trim throughout the module (discard existing arm knockers) | \$ 350.00 |
| 28 . Furnish and install rear entry door 4 place switch panel | \$ incl. |
| 29 . Furnish & install new base for captain's chair | \$ 400.00 |
| Needs the pin portion to slide in and out | |
| 30 . Furnish and drop ship Stryker Power Pro XT power load compatible cot per Stryker reference number 4704621. | \$ 23,250.00 |
| 31 . Furnish Stryker Power Load system | \$ 27,250.00 |
| 32 . Install Stryker Power Load with plating in base frame | \$ 1,500.00 |
| 33 . Replace floor with Alucabond subfloor and Lonseal vinyl floor - Sapphire (discard old) | \$ 3,100.00 |
| a) Remove and reinstall powder coated aluminum laydown O2 box with Lexan lid (discard old) | |
| b) Replace thresholds (discard old) | |
| c) Furnish & install Cot plates, hook and mount for a Stryker Power Load | |
| d) Remove & reinstall O2 rollers | |
| e) Remove & reinstall front I/O | |
| f) Remove & reinstall female seatbelts at squad bench | |
| g) Ship loose antler and bar | |
| Total | \$ 55,850.00 |

Terms and Conditions

- 1 . This quote is valid for 90 days.
- 2 . All pricing is F.O.B. Houston.

EXHIBIT 1

- 3 . Please note, payment for the entire purchase is due upon receipt and acceptance of completed unit.
- 4 . Please make your purchase order out to Knapp Chevrolet (P.O. Box 4179, Houston, TX 77210). Please email a copy of your purchase order and this quote to Bob Flanders with Knapp Chevrolet bflanders@knappchevy.com and to Adam Fischer at sales@frazerbilt.com.
- 5 . To minimize delays, customer provided items should be present prior to unit production start.
- 6 . Please remove your Onan generator and air conditioner prior to remount delivery at Frazer.
- 7 . Fair condition of module is assumed when quoting paint. Large or excessive dents, deep or excessive scratches and unforeseen body work will require a revision to the quoted paint price.
- 8 . Frazer will provide a weight slip with accompanying scale calibration certification. Your local vehicle registration office may require a state certified weight slip for registration. Should that be the case, you will need to weigh the vehicle at a local weigh station that provides a weight slip with the department of agriculture seal prior to registration.
- 9 . *Striping and lettering pricing may be adjusted based on the company's scheme. Striping and lettering pricing includes two hours' design time in the base price. Additional design time for more extensive graphics and/or multiple changes is quoted at \$100/hour.

Thank you for the opportunity to quote this job. If you have any questions please call me at 888-372-9371.

Best Regards,



Erika Fullick
Inside Sales Representative
Frazer, Ltd.